



### Cooling Tower Inspection and repair services

As you are already well aware we currently represent Marley, the largest cooling tower company in the world. We also offer a variety of cooling tower rehab and repair services. These projects can be catered to the specific needs of our customer. Cooling tower inspections can spot problem areas and prevent catastrophic failure, which can translate to cost savings. We have worked with several very large facilities in the area that depend on their towers in order to conduct business. Proper maintenance and care can also extend the longevity and decrease operating costs for the end user. One of our recent projects was a Marley NC (3) Cell located at Williams College (Berkshire County, MA). This project incorporated fill replacement, Basin Seam Sealing and comprehensive preventative maintenance on the towers.



All material and debris were hoisted on/off the roof via mobile crane service. We incorporate a crane lift into a majority of our projects, this significantly cuts down on labor hours.



*This is a picture taken prior to the repair. There is a large amount of scaling and debris built up on this fill. Fouled fill can greatly reduce the ability of the cooling tower to transfer heat.*



*Fill was replaced with Marley MX75. MX75 incorporates highly efficient cellular drift eliminators, integrally molded within the fill sheets. The single most important component of a cooling tower is the fill. \*MARLEY MX75 Brochure*

**Please feel free to reach out to us for your Cooling Tower needs. We perform inspections/ repairs on all cooling tower makes and sizes.**

**To Schedule an appointment please contact: Dillon E Barbeito 518-383-2111 EXT:416**